

## INSTALLATION

1. Turn off power.
2. Align template [C] and overlap holes at both ends to mark locations of (3x) mounting pegs [D].
3. Install pegs to blocking using (3x) #8-32 CSK screws [E] (by G.C).
4. Install REMOTE DRIVER ENCLOSURE [H] to building structure and attach BUILDING POWER using U.L. approved wire connectors. Run wiring from remote to standard 4.0 J-BOX [A] using at least 12AWG wiring and connect wiring (by E.C).
5. Place fixture pegs in blocking such that pegs sit in center holes in mounting blocks [F].
6. Secure fixture with (1x) #8-32 set screw [G] per mounting block (provided by company).



